

PALMERA
FURNITURE


MADE IN
NETHERLANDS


MADE IN
NETHERLANDS

PALMERA
FURNITURE


Black Pitch 150325


White 150101


Silver 150300


Suffolk Stone 150305


Moles Paw 150302


London 150120




MADE IN
NETHERLANDS

PALMERA
FURNITURE


Marsala 150236


Ochre 150204


Rust 150248


Charlston 150112



Chalk 150108


Elephant 150105




MADE IN
NETHERLANDS

PALMERA
FURNITURE



Navy Blue 150425




Patrol 150412



MADE IN
NETHERLANDS

PALMERA
FURNITURE







## Specification

| | | |
|---|---|---|
| Construction | : | Tufted 1/10 cut pile |
| Pile Material | : | Faux Silk |
| Secondary Backing | : | Luxury Backing |
| Pile Weight | : | ca. 1.85 kg / sq mtr +/- 7.5% |
| Total Weight | : | ca. 2.60 kg / sq mtr +/- 7.5% |
| Carpet Thickness | : | ca. 14 mm +/- 7.5% |
| Usage Classification EN 1307:2014 | : | Class 33 / Heavy Commercial use |
| Comfort rating EN1307:2014 | : | LC 5 |
| Static Electricity Charge | : | Anti static |
| Light ISO 105 B02:2013 | : | 5-6 |
| Rubbing - Dry ISO 105 X12 | : | 4-5 |
| Rubbing - Wet ISO 105 X12 | : | 4-5 |
| Water ISO 105 E01 : 2013 | : | 4 |
| Water Stains En1307 / EN15115 | : | 4-5 |
| TOG rating | : | 1.64 |
| Burn Behaviour BS EN ISO 9239-1:2002 | : | Bfl-S1 |
| Stair Suitability | : | Yes |
| Widths | : | 4mtr +/- 1% |
| Cut Length service | : | Yes |
| Standard Rug sizes | : | No |
| Bespoke Rug service | : | Yes |

**Matching:** This sample may not be from the same batch as current stocks and should be used only as a guide.

**Installation:** Professional installation is recommended and essential to a good quality underlay. Avoid exposure direct sunlight. Areas that might receive prolonged exposure to direct sunlight should be protected by the use of blinds or curtains.

**Maintenance:** To maintain your carpets appearance it is recommended that it is vacuumed at least three times per week to remove particles of dirt and dust. It should be noted that overtime foot traffic will flatten the pile in main walkways causing areas of differential wear. This can cause the carpet to show areas of light and dark shading, this happens to all quality of velour carpets and would not be accepted as a basis of any complaint.